


FIG. 1




**FIG. 2**

FIG. 3






FIG. 4



TUE020/Z5886860

FIG. 5



TUE 04/10 12:58:33 2000

FIG. 6







FIG. 7



**F I G. 8A**



**F I G. 8B**






**FIG. 9**

FIG. 10



T0E0X0 " 5886860

FIG. 11



**F I G. 12**

PARAMETER		LENS VALUE	CAMERA VALUE
X-AXIS ERROR	ANGLE	O1	C1
	SHIFT	O2	C2
Y-AXIS ERROR	ANGLE	O3	C3
	SHIFT	O4	C4

TOKYO "25886860

FIG. 13




FIG. 14

14/24





FIG. 15



09898857 - 070301

FIG. 16  
100"  
17'  
19'  
200"




FIG. 17

17/24




FIG. 18






FIG. 19




TDE020 25886860


**FIG. 20A**




**FIG. 20C**




**FIG. 20B**




**FIG. 21A**



**FIG. 21B**



**FIG. 21C**



**F I G. 22**




FIG. 23





FIG. 24



1020700 "58826860